
HUC: 15020003**Carrizo Wash**

Crater Lake**Carrizo Wash**

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Monitoring Schedule:	Assessed Date:	IR Category:
NM-9000.B_033	5	unclassified	2004	1/1/1998	1

Use Information:**Designated Use (s):****Attainment:**Livestock Watering
Wildlife HabitatFully Supporting
Fully Supporting**Assessment Information:****Assessment Unit Comments:**

El Caso Lake**Carrizo Wash**

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Monitoring Schedule:	Assessed Date:	IR Category:
NM-9000.B_038	80	unclassified	2004	1/1/1998	1

Use Information:**Designated Use (s):****Attainment:**Livestock Watering
Wildlife HabitatFully Supporting
Fully Supporting**Assessment Information:****Assessment Unit Comments:**

Little El Caso Lake**Carrizo Wash**

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Monitoring Schedule:	Assessed Date:	IR Category:
NM-9000.B_075	10	unclassified	2004	1/1/1998	1

Use Information:**Designated Use (s):****Attainment:**Livestock Watering
Wildlife HabitatFully Supporting
Fully Supporting**Assessment Information:****Assessment Unit Comments:**

Quemado Lake**Carrizo Wash**

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Monitoring Schedule:	Assessed Date:	IR Category:
NM-9000.B_096	111.89	unclassified	2004	1/1/1998	5/5A

Use Information:**Designated Use (s):****Attainment:**

Coldwater Fishery

Not Supporting

Livestock Watering

Fully Supporting

Warmwater Fishery

Insufficient Information

Wildlife Habitat

Fully Supporting

Assessment Information:**Probable Causes of Impairment:****TMDL Schedule:**

Nutrient/Eutrophication Biological Indicators

2017

Sedimentation/Siltation

2017

Probable Sources of Impairment:

Loss of Riparian Habitat

Natural Sources

Other Recreational Pollution Sources

Rangeland Grazing

Silviculture Harvesting

Streambank Modifications/destablization

Assessment Unit Comments:

HUC: 15020004**Zuni**

Cebolla Creek (Rio Pescado to headwaters)**Zuni**

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Monitoring Schedule:	Assessed Date:	IR Category:
NM-9000.A_031	7.93	unclassified	2004	1/1/1998	3

Use Information:**Designated Use (s):****Attainment:**Livestock Watering
Wildlife HabitatNot Assessed
Not Assessed**Assessment Information:****Assessment Unit Comments:**

McGaffey Lake**Zuni**

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Monitoring Schedule:	Assessed Date:	IR Category:
NM-9000.B_083	10.94	unclassified	2004	1/1/1998	5/5A

Use Information:**Designated Use (s):****Attainment:**Coldwater Fishery
Livestock Watering
Warmwater Fishery
Wildlife HabitatNot Supporting
Not Assessed
Not Supporting
Fully Supporting**Assessment Information:****Probable Causes of Impairment:****TMDL Schedule:**Nutrient/Eutrophication Biological Indicators
pH
Sedimentation/Siltation2017
2017
2017**Probable Sources of Impairment:**Highway/Road/Bridge Runoff (Non-construction
Related)
Impervious Surface/Parking Lot Runoff
Loss of Riparian Habitat
Natural Sources
Streambank Modifications/destablization**Assessment Unit Comments:**

Lake often goes dry. Department of Game and Fish dredged the lake in 2003 to return it to its original design capacity. They no longer stock trout (just catfish when there is adequate water).

Rio Nutria (Zuni Pueblo bnd to headwaters)**Zuni**

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Monitoring Schedule:	Assessed Date:	IR Category:
NM-9000.A_029	11.8	unclassified	2004	1/1/1998	5

Use Information:**Designated Use (s):**

Livestock Watering
Warmwater Fishery
Wildlife Habitat

Attainment:

Not Assessed
Not Supporting
Fully Supporting

Assessment Information:**Probable Causes of Impairment:**

Mercury

TMDL Schedule:

2007

Probable Sources of Impairment:

Source Unknown

Assessment Unit Comments: